CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This material contains information assecting the Raislonal Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 783 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

	C-O-N-F-I-D-E-N-	F-I-A-L		25X1
COUNTRY	Korea Rehabilitation of Heavy Industry in North Korea		25 April 1955 2	25X
DATE OF INFO		REQUIREMENT NO. RD		
LACE ACQUIR	EC	REFERENCES		25 X 1
	This is UNEVALUATED Information			
	THE SOURCE EVALUATIONS IN THIS REP THE APPRAISAL OF CONTENT IS (FOR KEY SEE REVERS	TENTATIVE.		25X′
t:	the P'yongyang spenabilitated and were in operation, officen in KIM Il-song Plaza, and the Morang and Czechoslovak technicians had performed Soviet machinery had been used in the	ong Theater was completed. ed the technical work on the	construc- Soviet	25 X 1
2. Ir op du ro 3. Ti	Huich'on (N 40-10, E 126-16) (BV6849), peration, the factory installations consuming the war had been reinforced against ows of three-story buildings with complete Hwanghae Iron Works in Hwanghae Province 129-50) (EB6925) and Kimchael een almost completely rehabilitated and	the automobile factory was structed underground near Ho it possible future bombing, ete basements had been erect vince and heavy industry in a (N 40-40, E 129-12) (EA170	and ted.3	
	Comments	•		25 X 1
1. P	robably the P'yongyang Textile Works is P'yongyang Radio reported that	meant. this company had begun ope	erations.	25X ²
2.				25 X 1
3• H	the uich'on Machine Works had begun operation stablishment with the latest equipment.	Huich'on Auto Parts Factory ons the latter was		25X1 (1
	C-O-M-F-1-D-E-M	-T-I-A-L		05111
				25 X 1

(NOTE: Washington distribution indicated by "X"; field distribution by "#".)

	- 2 -		
Comment.			
Comme			
tion of the la	a ceremony was held marking com	olete rehabili-	2
	according to P've	ngvang Radio.	25
second open :	furnace was put into operation	*****	25
	restored, which was double the capacity of I	self was in	25
eration it was	though the works it highly unlikely the rolling mills could be a per second because excessive repairs were require	self was in	25 2
eration it was	though the works it highly unlikely the rolling mills could be r	self was in	
eration it was	though the works it highly unlikely the rolling mills could be r	self was in	2
eration it was	though the works it highly unlikely the rolling mills could be r	self was in	2
eration it was	though the works it highly unlikely the rolling mills could be r	self was in	2

C-O-N-F-I-D-E-N-T-I-A-L